

Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

January 23, 2013

CERTIFIED RETURN RECEIPT 7011 0110 0001 3568 0444

Kenichi Toma United Minerals, LLC 400 South 100 East Emery, Utah 84522

Subject: Division Directive, United Minerals, LLC, TRC Mine S0150098, Emery County, Utah

Dear Mr. Toma:

The last surety estimate for the TRC Mine was done in 2009 and escalated to 2012 dollars. The surety amount is now due for review and possible adjustment, but in reviewing the surety and the Notice of Intention to Commence Small Mining Operations (NOI), some discrepancies and deficiencies have been found.

No later than February 28, 2013, please provide the following:

- Two maps as follows:
 - A general location and direction map at a scale of about 1:24,000. The map currently on file is a fax copy and is poor quality. It shows a new access road (included as part of the permitted and bonded area), but it needs to also show how to get to the site from a paved road, or geographic location, such as S. R. 10 or Emery. It may be necessary to use more than one map.
 - A permit boundary map at a scale of about 1"=200'. Please show the locations of any mine facilities, such as portals, soil and overburden piles, equipment (scalehouse or similar items), etc.
- Please provide an updated page showing the number of acres of disturbance. The Division has conflicting information about the size of the disturbed area. Please see the enclosed pages. The correct value should include acreage for the access road (4.06 acres) and the pad (0.126 acres) for a total of 4.18 acres, but these values are on the older version of the NOI.
- Please list the number of openings and approximate dimensions.



Page 2 of 2 Kenichi Toma S/015/0098 January 23, 2013

Please submit these changes as an amendment to the NOI using form MR-REV-SMO/EXP available on the Division's web site at https://fs.ogm.utah.gov/pub/mines/minerals_related/forms/MR-REV-SMO_EXP.pdf.

Thank you for your help in keeping the surety and NOI current. Please contact Wayne Western at 801-538-5263 or me at 801-538-5261 if you have any questions concerning this letter.

Sincerely,

Paul B. Baker

Mining Program Manager

PBB: whw: eb

Enclosure: Two pages from the NOIs

cc: jblake@utah.gov